User:

Friday, 04/04/2008 9:21:57 AM

Julie Lecocq

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

S.O. No. :

Job Number : 38392 : 10510 **Estimate Number**

P.O. Number

This Issue : 04/04/2008

: NC

: //

: 33321

: PURCHASED PARTS Type

Part Number

Drawing Name

: D25763

: STEP (CASTING DETAIL)

Drawing Number Project Number : D2576 REV G : N/A

Drawing Revision

: G Material

Due Date

Qty:

100 Um:

Each

Written By

Prsht Rev.

First Issue

Previous Run

Consolidated D2576-1 and D2576-3

KJ/RF

: 14/04/2008

Checked & Approved By

Comment

Est Rev:D As per Rev G 07-09-05 JLM Verified By:EC

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

D25761

Step (Casting Detail)



Comment: Qty.:

1.0000 Each(s)/Unit Total: 100.0000 Each(s)

Pick:

Qty

Part#

Description D2576-1 Step (Casting Detail)

2.0

HAAS1

HAAS CNC VERTICAL MACHINING #1



Comment: HAAS1

1- Machine as per Folio FA332 and Dwg D2576

3.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

SECOND CHECK



Comment: SECOND CHECK

5.0

PACKAGING 1

PACKAGING RESOURCE #1





Comment: PACKAGING RESOURCE #1

Identify and Stock





Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	

NCR: ろ	5570	Corrective Action Section B				T		
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
3/06/33	2	Myparts lifted while machining dimension 128 is under tolerand 2 one parts acceptable? Re operator every meren't sitting Plat as in use	Bour	Scrap cul Destry no Replace Dry (2)	エト	08/05/38	posiul L	OST osta
		·						

NOTE: Date & initial all entries

Date:

Friday, 04/04/2008 9:21:57 AM

User:

Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: STEP (CASTING DETAIL)

Job Number: 38392

Part Number: D25763

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC21

FINAL INSPECTION/W/O RELEASE



08/05/29/

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



MF 08-05-2

Dart Aerospace Ltd

Duitho	·oopao								
W/O:			WC	ORK ORDER CHANGE	ES				
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
<u>.</u>									
Part No) :	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _	
					QA: N	I/C Close	d:	Date: _	
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NCF	?)			
D.4.T.E.	STEP	Description of NC	Corrective Action Section B			Verific	Verification	Approval	Approval
DATE		Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Sect	ion C	Chief Eng	QC Inspector
								t 	
,									

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	38392
Description: Step	Part Number:	D2576-3
Inspection Dwg: D2576 Rev: G		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

x	First Article	Prototype
---	---------------	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
7.50	+/-0.030	7.50				
Slot 0.250 x 1.25	+/-0.030	251X1.25				
Slot 0.250 x 0.65	+/-0.030	250 X.650				
Slot 0.250 x 1.28	+/-0.030	.250X/.28				
0.19	+/-0.030	.190				
0.13	+/-0.030	136				
0.063	+/-0.010	Fe0-				
					1	
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
-						
		177			.,	
		, so				-
	- "		-			

Measured by:	ゴル	Audited by:	Prototype Approval:	N/A
Date:	08/05/22	Date: 28-05-76	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	04.02.10	New Issue	KJ/RF	
В	07.09.06	Dimensions updated per Dwg Rev G	KJ/JLM	B
			1.01	

